

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 98-25584

INITIAL CUSTOMER ORDER NO

W/3 SPENT CASES

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/30/98

12/01/98

KP 5-95

T6211569

700 308

SS/DM/SYN

ACCESSORIES

W/STUDS

FROM

SHIP TO

PENNINGTON TERRY R.
142 R. PENNINGTON SR.
TALLAHASSEE

FL 32312

PENNINGTON TERRY R.
142 R. PENNINGTON SR.
TALLAHASSEE FL
32312

CUST NO: 199267 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

12/4

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

* Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A

B1

Excessive headspace

TRIGGER GROUP

B2

Difficult extraction - case expansion

BOLT ASSY.

B3

Fires on Bolt closing

BARREL ASSY.

B4

D1

E3

F2

REC. ASSY.

B5

D2

E4

F1

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Bolt thread broken from firing pin
Lugger Pin. Lugger pin seized up, not from unknown
source. Bolt fired once and released

PARTS

COMMENTS

1. Replace Trigger Group w/ N/C
2. Send out for ball of repair needed
3. Check headspace

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7-97

PS04914