

PEORIA POLICE DEPARTMENT
SPECIAL RESPONSE TEAM

Remington Arms Company, Inc.
Arms Service Division
Ilion, Ny. 13357

Sgt. J. W. Adams
Peoria Police Dept.
600 S. W. Adams
Peoria, Ill. 61602-1592

Dear Sirs:


Enclosed is one of our Special Response Team's model 700 P (DM) rifles. This rifle is assigned to one of the team's snipers. This weapon is allowing the firing pin to strike the primer as the bolt is being place in battery. The weapon has exhibited this characteristic on three occasions. The weapon has not discharged as the strike on the primer has been too light.

An additional problem has surfaced. A round is chambered while the safety is engage. Upon releasing the safety, the firing pin launches forward as if the trigger has been pulled. This problem was discovered while inspecting the above problem.

Further, the barrel is not seated properly in the H-S stock. The barrel is visibly touching the fiberglass stock towards the end of the forearm.

Please repair and return as soon as possible. This weapon is one of four active Remington 700-P rifles currently in use by our team.

Thank you,


Sgt. J. W. Adams