

Remington Arms Attn: Consumer Repair TPA 14 Hoefler Avenue Ilion, NY 13357

To Whom It May Concern:

Enclosed please find my Remington Arms Mohawk 600. It is a 308 caliber with a serial number of 6646545. I purchased it about 27 years ago as a used firearm from a NH licensed dealer. I am aware that there are two recalls on this firearm. One was many years ago for a faulty trigger mechanism. The other was for a more recent recall for a problem bolt design. Kay in your customer service was very helpful in checking the warranty info for me

I feel I should provide some information for your database. I have had two accidental discharges while I have owned the weapon. Once was on a cold NH afternoon while unloading with a friend at our car. I was unloading with the muzzle down and in a safe direction. The firearm discharged. I never understood what I might have done wrong. The second time was last year at a camp firing range in Anticosti Canada. I loaded the weapon, took careful aim, pulled the trigger and then realized I had not released my safety. With the rifle on a bench rest and pointed downrange, I released the safety. The firearm discharged with my hand definitely away from the trigger. I am providing this information with the desire it may contribute to your continued efforts to provide safe products in this litigious world in which we live.

Kay said normal turnaround for the warranty repair is typically 3-4 weeks. I will be returning to Anticosti on October 2. I would love to bring this rifle as it has many memories stored inside. I understand that this may not be possible. This rifle has brought me years of enjoyment. I appreciate the concern of your organization to make it safe.

Thanking You in Advance,

Dana C Pinney

224 Old Homestead Hwy East Swanzey, NH 03446

Work Phone 603-357-0944 Evening Ph 603-357-0944