

RECEIPT AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R 94-21734

TIAL CUS. ORDER NO.

PS
DATE RECEIVED 7/21/94 DATE OPENED 07/21/94 DATE CODE LK 2-90 SERIAL NUMBER C6501204 NEW SERIAL NUMBER MODEL AND GRADE 700 223 REM BDL/VAR
ACCESSORIES W/STUDS SCOPE BASE

FROM: *Set up*
PETERSON, JASON
1394 GUS GRIND
FAIRBANKS

AK 99709

SHIP TO:
PETERSON, JASON
1394 GUS GRIND
FAIRBANKS

AK
99709

CUST NO: 100321 C.O.D L

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
IN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED					REPAIR CHARGE <i>200</i> EXCISE TAX INSURANCE <i>500</i> UPS PARCEL POST TOTAL <i>8800</i>

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
FOOD			C1	D3	E5	F5
ETAL			C2			

MAIN FAULT
Examination revealed that the trigger assembly (dependent) was not properly engaged and was loose in the gun. The trigger was in the down position. A pin in the trigger is present on all trigger guns. We could not duplicate the malfunction.

ARTS	COMMENTS
# 26345	<i>Examine the trigger assembly and when action at 1/2 the normal speed, as per spec. of good will</i> <i>Go ahead</i>
REPAIRMAN J.A.L.	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RD6925 REV. 1/94

PS04943