



Pulaski County

Office of the Sheriff

Randy Johnson, Sheriff

2900 South Woodrow Little Rock, AR 72204

Tel. 501-340-6600

Lyle Wheelock
Remington Arms Company
1-29-03

Enclosed in the box is the Sniper rifle (D6272160) I discussed with you on the phone. The sniper operator stated that when he moved the safety from safe to firing position the weapon discharged without touching the trigger. He repeated this process six times and the weapon fired each time by moving the selector from safe to fire. When he brought in the rifle and I moved the selector to fire from safe and the weapon fired. I took the stock off the rifle and cleaned the trigger assembly with rem oil without taking the assemble apart or off the weapon. I repeated the process of moving the safety switch to the firing position and the rifle fired again without touching the trigger. I repeated this five more times, each time cleaning the trigger area by spraying rem oil in the trigger area. It fired two out of five times that I move the safety to the fire position.

Since this is a police sniper weapon you can imagine our concern about the weapon discharging without pulling the trigger. For our sound of mind we are requesting that only Remington Arms Company makes the necessary repairs or adjustments and advices us in writing that the weapon is fit for police sniper operations.

Simon P. Haynes
Sgt. Simon Haynes
Pulaski County Sheriff's Office
2900 S. Woodrow
Little Rock, Ar. 72204

Phone number 501-340-6966

*2/3/03 should trigger housing duty /
trigger pin duty - Poor Maintenance*

Serial Number: **D6272160**
Model: **700**

RE00060906

*Replace trigger assembly at no charge
Goodwin Charge 230145*