

ORDER
R 92-21775

ATTN: JIM STEKL

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/13/92	10/19/92	PQ-6-78	A6626021		700 30-06 BDL
ACCESSORIES	W/STUDS				

L/REAR SIGHT

FROM:

SHIP TO:

DUNCAN SPORT SHOP
414 SECOND ST
N WILKESBORO

NC 28659

DUNCAN SPORT SHOP
414 SECOND ST
N WILKESBORO

NC
28659

CUST NO:004603 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED	
-----------	--

VIA

UFS

GUN CONDITION

☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE	A1	B1				
TRIGGER GROUP	1) "	B2	has fired on two occasions while	E1	F1	
BOLT ASSY.	from	B3	"safe" position to "fire" position	E2	F2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.	2) Shock	B5	"just cracked" - no misuse" -	E4	F4	
WOOD				D3	E5	F5
METAL				C2		

MAIN FAULT:

- 1) cannot duplicate complaint - rft and safety operate properly in every respect. Trigger pull 3 1/4 pounds; wear life ~ 008"
- 2) this is old grade - post wood warranty - rft produced 6/78
this crown does not weaken stock at all.

ARTS

COMMENTS

- 1) Offer the following option: a) return ship ad- to pt offer to replace truss asseably at $\frac{1}{2}$ normal cost as gesture of good-will, if that will better restore confidence in the r/c
- 2) estimate cost to repair cradle - be as possible.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92

PS05013