

File Number:	18048		Arms Service number:	52886	
Last Name:	QUINN		First Name:	R W	
Street:	250 HERMAN ROAD		City:	REIDSVILLE	
State:	NC	Zip:	27320	Home Ph:	336-342-6543
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	9/30/2002	Date Opened by P/S:	10/1/2002	Caliber:	3006
Date of Incident:		Date Closed:	10/2/2002	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	B6281549	Date Code:	BB
RAMAC:	700	Litigation:		PreLitigation:	
Custody:		Obsolete:			
Time of Modification:	8 39:18 AM	Comments: TA so sticky that the sear is stuck to the sidewalls of the housing. The TA settings have also been altered creating an unsafe condition - Stop release out of position. Quote new TA, clean action \$20 under bolt lock modification program Shipping and Repair documents 10/17/02			
Date of Modification:	10/2/2002				