

Repair Order Number



Repair Order Number RE00052886	Description/Serial Number B6281549	Repairman - Herb Brown
Account # - R-	Model 700 Center Fire Caliber: 3006 BDL	Date Received - 10/3/2002
		Estimate Date - 10/2/2002
		Current Date - 10/14/2002
Customer RONALD OOUINN 250 HERMAN RD REIDSVILLE, NC 27320 US		Return To RONALD OOUINN 250 HERMAN RD REIDSVILLE, NC 27320 US
Phone (H) (336)-342-6543		
Phone (W)	Fax	Email

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE	M123	FORWARD TO PRODUCT SERVICE F
	FOR INSPECTION	M238	CLEAN & INSPECT
M238	CLEAN & INSPECT	M239	REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F26345		700 TRIG ASSB RH	1	1	0	Y
Part Total:			1	1	0	
Service						
4000294		GR-CHECK TPA	1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116		GR-LABOR	20	20	0	N
4000118		GR-CLEAN	1	1	0	Y
4000119		GR-TEST	1	1	0	Y
Service Total:			23	23	0	

Condition	REC'D W/ MINOR WOOD MARS & WOOD BLEM. REC'D W/ BOLT RELEASE NOT WORKING.				
ProblemNotes	Sear stuck to side walls of sear housing. Trigger assm. settings altered creating unsafe condition. Bolt stop release out of position. Quote for new trigger assm. under bolt lock modification program				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 MOEFER AVE
ILION NY 13357

SHIP

TO:

RONALD OQUINN
250 HERMAN RD
REIDSVILLE NC 27320




NC 274 9-04



UPS GROUND

TRACKING #: 1Z 114 813 03 1196 3007



BILLING: P/P

INV#: RE00052886

ASC 05.00 J69X/J64X 16.0A 01/2002