



Ronald O'Quinn
250 Herman Rd.
Reidsville, NC 27320-8929

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: B6281549	
Name: R.W. O'Quinn	Date of Purchase: 1983	
Address (no PO Boxes): 250 Herman Rd.		
City: Reidsville	State: NC	Zip: 27320
Phone (Daytime): (336) 342-6543	Fax:	
E-mail Address:		

Please describe your problem: Sometime The Trigger is hard
To pull - when you fire it + flip another round
in chamber it fires without pulling the
Trigger. (own its own)
(REAL dangerous)

Additional Information: (Ammo type, brand, handload specifications, etc.)

Remington 30-06 150 grain

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU NEED A SEPARATE PACKAGE AND INCLUDE NAME ADDRESS (WITH NUMBER OF YOUR FIREARM)

- :: Record the serial number of your firearm before sending
- :: Pack your firearm for safety and to prevent further damage in a firearm box. (Note: Original boxes may not be
- :: Remove all accessories from your firearm to prevent loss
- :: Ship your INSURED firearm by either UPS or Parcel Post damage or loss during shipment, so you may elect to purchase

Serial Number:

B6281549

Model: 700



RE00052886

Sear stuck to sidewalls of
Trigger Housing. TA settings
altered creating unsafe condition.
Bolt stop release out of position.

Quote \$20 for new TA and cleaning action under bolt lock
modification program.

FLS 10/1/02

<http://www.remington.com/support/repair/svc/repairform.htm>

3-22-2002

PS05032