

Number: 7757117

Model: 7



RE00029836

1/25/01 Exchanges when safety was taken
off

Upon receipt we could not duplicate
the Customs Concern —

Exam. noted a small machining
metal chip under the trigger housing.

Replace the trigger assembly at no charge

1007
4040

Chg 230145