Street: 861 FIVE PINES ROAD City: NORTH HUNTINGDON State: PA Zip: 15642 Home Ph: Work Ph: Product Type: F F A T O Type Concern: S PI PD P S Concern Code: 1007 Concern: FIRED ON SAFE RELEASE Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Work Ph: Product Type: F F A T O Type Concern: S PI PD P S Concern Code: 1007 Concern: FIRED ON SAFE RELEASE Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Type Concern: S PI PD PS Concern Code: 1007 Concern: FIRED ON SAFE RELEASE Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Concern: FIRED ON SAFE RELEASE Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Assigned To: SUPRY Classification: UND UNJ UNC UND Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
Settlement Detail: BLM PROGRAM Settlement Amount: \$65.00
D. C. I.D. Lorenza
Date Opened Rem: 3/5/2004 Date Opened by P/S: 3/5/2004 Caliber: 7MMMAG
Date of Incident: Date Closed: 3/5/2004 Bullet Weight:
Date to Analysis: Manufacturer:
Model: 700 Serial: 6282887 Date Code: ES Date Mfgd: 10/1/1969
RAMAC: 700 Litigation: PreLitigation: Obsolete:
Custody: Comments: Could not duplicate concern. Install new TA and clean action, \$20 under the bolt lock modification program. Scope ring was broken in shipment. Called customer let him.
Time of Modification: 9.48.01 AM know that the scope ring broke. We agreed not to charge the customer for the Bolt
Date of Modification: 3/5/2004 Lock Modification and in return the customer will take care of replacing the broken scope ring 3/8/04.