

Serial
Number:

6282887

Model: 700



RE00077865

Bruce Queen
861 Five Pines Road
North Huntingdon, Pa. 15642

February 8, 2004

ES = 10/69

To Whom It May Concern:

I am returning my Remington Model 700 7mm Magnum rifle as result of it having accidentally discharged twice. The first incident occurred during the 2002-2003 hunting season. I was unloading the rifle upon exiting the woods, as always, I had the muzzle pointed in a safe direction, switched the safety to the "F" position and started to open the bolt when, much to my surprise, the firearm discharged. I had never experienced this before and discounted the incident, thinking that I did something to cause the rifle to discharge.

When the same thing happened a second time during the 2003-2004 hunting season, I consulted a friend who advised me that Remington is known to have a problem with the Model 700 and that there have been several shooting incidents as result of the rifle accidentally discharging. He provided me with the recall information from your web site.

Fortunately for me, I practice proper gun safety and was not injured. It scares me to even entertain the thought of the firearm discharging while the bolt was partially open. I would greatly appreciate anything you do to help make my rifle as safe as possible.

Sincerely,

Bruce Queen

Could not duplicate. Install new
TA and clean action. Quote \$20
under the bolt lock modification
program.

Scope Ring Broken
during shipping

Fred 3/5/04

77865