

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-20714

IAL CUSTOMER ORDER NO.

ATTN J STEKL BOT F OF MTS ONLY
CLASSIC

DATE RECEIVED 01/01/92	DATE OPENED 10/08/92	DATE CODE 01 7-88	SERIAL NUMBER C6280426	NEW SERIAL NUMBER	MODEL AND GRADE 700 35	WHELEN
---------------------------	-------------------------	----------------------	---------------------------	-------------------	---------------------------	--------

M:

RAISLER, LOU
8546 W HOMOSASSA TRAIL ST #3
HOMOSASSA FL 32448

SHIP TO:

RAISLER, LOU
8546 W HOMOSASSA TRAIL ST #3
HOMOSASSA FL 32448

CUST NO: 067857 C.O.D.

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

CONDITION	REPAIR CHARGE
NEW	EXCISE
SLIGHTLY WORN	TAX
WORN	INSURANCE
VERY WORN	UPS
UNREPAIRABLE	PARCEL POST
DARRIED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
EE	A1	B1				
AGER GROUP		B3			E2	F2
T ASSY.		B4		D1	E3	F3
REL ASSY.		B5		D2	E4	F4
ASSY.			C1	D3	E5	F5
OD			C2			
AL						

Cannot duplicate complaint after many attempts - Turn in assembly
operating properly. However, disassembly of the receiver target assembly
reveals (screws have been tampered with outside for the contact missing from all
warrant screws) 1) insufficient rear engagement; 2) insufficient rear travel
pull 4# - pull off .010"
Check location of front gun screw location - insufficient clearance for screw

Pls foto - target
Supply

COMMENTS

1) After replacement target assembly at
normal contact will get time
2) Replace stock at N/C

REPAIRMAN	PRO	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS05087