

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER NO. **R 95-00582**

AL S. CUSTOMER ORDER NO.

RECEIVED DATE OPENED DATE CODE
1/27/94 01/06/95 100-1-28

SERIAL NUMBER
A6589261

NEW SERIAL NUMBER

MODEL AND GRADE
700 25-06

BDL

ESSORIES **W/STUDS**

M:

**RYBARIK, JIM
RD 8 BOX 239
KITANNING**

PA 16201

SHIP TO:

**RYBARIK, JIM
RD 8 BOX 239
KITANNING**

PA

16201

CUST NO: **162031 C.O.D.**

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

1-30

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRED

*High Pull - 6 lbs
Low Pull - 0.10*

REPAIR CHARGE **20.00**

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
GGER GROUP		B2			E1	F1
.T ASSY.		B3				
REL ASSY.		B4		D1	E3	F3
. ASSY.		B5				F4
OD				D5	E5	F5
TAL			C2			

FAULT

*Called May 1988, upon receipt, we could not duplicate the
original problem. However, we were advised that the trigger, bolt
top roller and rear sight can move around very slightly. The
trigger and trigger assembly are mounted with a very slight adjustment.
With much a good cleaning.*

26345

*Revised the complete trigger assembly
w/ roller the roller at 1/2 the normal
upside but as a gesture of good will
Go ahead*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>[Signature]</i>		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1-94

PS05123