

Repair Order Number



Repair Order Number RE00060620	Description/Serial Number 6304135	Repairman - Robert Frink Date Received - 2/20/2003
Account # - R-	Model 700 Center Fire Caliber: 22250 ADL	Estimate Date - 2/4/2003 Current Date - 2/26/2003
Customer LEON RUSSELL 6208 HWY 460 W WEST LIBERTY, KY 41472 US	Return To LEON RUSSELL 6208 HWY 460 W WEST LIBERTY, KY 41472 US	
Phone (H) (800)-354-7402 XW Phone (W) (606)-743-3397 XH	Fax Email	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRE BEFORE TRIGGER WAS PULLED		

<u>Material #</u>		<u>MaterialDesc</u>	Repair			
			<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part						
F26345		700 TRIG ASSB RH	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116		GR-LABOR	20	20	0	N
4000118		GR-CLEAN	1	1	0	Y
4000119		GR-TEST	1	1	0	Y
Service Total:			22	22	0	

ProblemNotes	Trigger assembly dirty, parts seized up or moving sluggish. Poor maintenance. Replace trigger assembly \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date