

Remington

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00061524	Description/Serial Number 6434227	Repairman - Robert Frink
Account # - R-	Model 700 Center Caliber: 6 MM	Date Received - 2/26/2003
Customer EDWIN REID 3003 TWIGG ST PALATKA, FL 32177 US	BDL	Estimate Date - 2/18/2003
Phone (H) (386)-325-5077		Current Date - 3/6/2003
Phone (W)		Return To EDWIN REID 3003 TWIGG ST PALATKA, FL 32177 US
	Fax	
	Email rcr@gbso.net	

Reported	Found
M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION
	M125 STOCK CRACKED

<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F103600	700 STK ASSB BDL S/A	1	1	0	N
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		2	2	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

Problem/Notes	Action and trigger assembly covered with a brown substance - Poor maintenance. All 3 adjustment screws re-set. Clean action and replace trigger assembly \$20.00. Supply new stock at 1/2 normal price. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date