



Repair Order Number

Repair Order Number RE00059723	Description/Serial Number C6800526	Repairman - Robert Frink Date Received - 1/20/2003
Account # - R-	Model 700 Center Fire Caliber: 308 PSS	Estimate Date - Current Date - 1/31/2003
Customer RAMCO 10700 HAMES BLVD MUSTANG, OK 73064 US		Return To RAMCO 10700 HAMES BLVD MUSTANG, OK 73064 US
Phone (H) (405)-376-2360 Phone (W)		Fax (405)-376-5632 Email grbullet@msn.com

Reported		Round	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WHEN BOLT WAS CLOSED		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	N
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119	GR-TEST	1	1	0	N
Service Total:		1	1	0	

ProblemNotes	Could not duplicate. Sticky residue. Installed new trigger assembly at 1/2 normal charges. Mfg 4/93. FLS 1/24/03.				
Repairman	Proof	Clean	T	Target	Pattern
Gallery Tester	Date	Date	I	Date	Date