

Remington Arms Company, Inc.

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00073978 Account # - R-	Description/Serial Number F6237161 Model 700 Center Fire Caliber: 300 WIN MAG SYN CAMO	Date Received - 12/12/2003 Estimate Date - Current Date - 12/18/2003
Customer VOCTOR ROSE 125 KNOLL AVE CRAIG. CO 81625 US	Return To VOCTOR ROSE 125 KNOLL AVE CRAIG. CO 81625 US	
Phone (H) (920)-924-1497 XWK Phone (W) (970)-824-5160 XHM	Fax Email nvroses@amigo.net	

Reported		Problems	Found
M992	UNINTENTIONAL FIRING	M123	FORWARD TO PRODUCT SERVICE FO

Technician's Comments	
Problem/Notes	upon receipt could not duplicate the reported concern. more than normal force was required to move safe arm...a small metal machining chip was found inside the trig housing assem. replace complete trig assem. no charge per prod service

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		2	