

Serial
Number:

F6237161

Model: 700



RE00073978

12/15/03

Date Coll
RW 11/02

Upon receipt we could not

duplicate the reported concern -

More than normal force was required
to move sub arm & a small metal

marking chip was found inside the
tug housing assembly.

Repair completed tug assembly at

NO Charge

Charge

nan 11