

Repair Order Number



<b>Repair Order Number</b> RE00083790	<b>Description/Serial Number</b> 161893	<b>Repairman -</b> Bruce Travis
<b>Account # - R-</b>	<b>Model</b> 722 Center Fire with 26 inch barrel <b>Caliber:</b> 222	<b>Date Received -</b> 9/10/2004
<b>Customer</b> SPORTSMANS WAREHOUSE 3797 EAST FAIRVIEW AVE MERIDIAN, ID 83642 US		<b>Estimate Date -</b> 8/16/2004 <b>Current Date -</b> 9/20/2004
<b>Phone (H)</b> (208)-884-3000 <b>Phone (W)</b> (208)-888-6939		<b>Return To</b> SPORTSMANS WAREHOUSE 3797 EAST FAIRVIEW AVE MERIDIAN, ID 83642 US
	<b>Fax</b> (208)-884-3100 <b>Email</b>	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRE WHEN TAKEN OFF SAFE		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000116	GR-LABOR	20	20	0	N
Service Total:		21	21	0	

<b>ProblemNotes</b>	firing pin follows down as received, trigger assm set screws altered. replace complete trigger assm under bolt lock safety program for \$20.00.				
<b>Repairman</b>	<b>Proof</b>	<b>Clean</b>	<b>Test</b>	<b>Target</b>	<b>Pattern</b>
<b>Gallery Tester</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>