

ATTN: P.S.

Repair Order Number



Repair Order Number
RE00001379

Description/Serial
E6557991

Repairman - Bruce Travis
Date Received - 1/14/2000

Account # - R-

Model 700 Center Fire300 ULTRA MAG
BDL ENHANCED

Estimate Date -

Current Date - 1/14/2000

Customer
CHRIS REGILSKI
20 VAN BUREN ST

Return To
CHRIS REGILSKI
20 VAN BUREN ST

ALBANY, NY 12206 US

ALBANY, NY 12206 US

Phone (H) (518)-458-2531 XDAY

Fax

Phone (W)

Email

Problems

Reported

M005 Bolt Handle fell off
ROUND DI SCHARGED REMOVING BOLT
SAFETY D OES NOT WORK

Found

Repair

Material # MaterialDesc

Quantity
Needed

Quantity
From

Quantity
From

Warranty
(Y/N)

Service

4000104 ARMS SERV SHIPPING & HANDLING

Service Total:

1
1

1
1

0
0

Y

1020
4040
Could not duplicate the firing on warning belt
Belt handle is damaged (not straight)
Replace the trigger assembly & belt drum at
no charge. Check 230145

ProblemNotes

SENT TO PRODUCT SERVICE FOR EVALUATION

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date