

Date: 2/15/05

By: Bruce Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Jeffery W. Rexrode

R.E. Number: 92880

Reason for inspection: FSR

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: C6742034 Date of Manufacture: 9/92

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: DIRTY/STICKY

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 5#

Manual safety: OKAY

Test firing results (if applicable): _____

DISPOSITION

Could not duplicate concern. Trig. assm. Dirty/sticky from
A. Dried lubrication residue. Replace TPA & check lower
Function test. change 1/2 MSP quote

ADDITIONAL COMMENTS