

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO		COMMENTS ATTN J STEKL			
DATE RECEIVED 01/18/90	DATE OPENED 01/25/90	DATE CODE AW 3-72	SERIAL NUMBER 6536430	MODEL AND GRADE 700 243 BDL		ORDER R 90-03053	
ACCESSORIES W/STUDS							

FROM:

**FRANK RUBIK
OLD RT 17
LIVINGSTON MANOR NY 12758**

SHIP TO:

**FRANK RUBIK
OLD RT 17
LIVINGSTON MANOR NY
12758**

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	--	--	--	--	--	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"It has developed a habit of firing when the safety is released and an attempt to fire, it doesn't fire, then when I go to eject the unfired casing it fires as the bolt starts upward".

MAIN FAULT

PARTS

Unable to duplicate complaint - Trigger pull 5 1/4 #, rear lift .0095". Disassembly of rifle revealed bottom of action & trigger assembly very dirty & gritty - Trigger assembly contaminated with dirt and excessive oil.

Per phone conversation with owner on 2/9/90 - clean present assembly, nitrid and return.

Charge \$10 to handling + return postage

*2/9/90
JAS.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS05202