

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN J STEKL

INITIAL CUSTOMER ORDER NO.

LCS

DATE RECEIVED

10/04/90

DATE OPENED

10/12/90

DATE CODE

KY 5-74

SERIAL NUMBER

6749628QQQ

MODEL AND GRADE

700

30-06

ADL

ORDER

R

90-26525

ACCESSORIES

L/SIGHTS

SCOPE BASE

FROM:

ROYAL ARMS
5608 KITSAP WAY SUITE 1
BREMERTON WA 98312

SHIP TO:

ROYAL ARMS
5608 KITSAP WAY SUITE 1
BREMERTON WA
98312

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☒ VERY WORN

☐ MISUSED

☒ MARRED

CUSTOMER'S REQUEST

"It has had 3 accidental discharges when safety is released"

MAIN FAULT

Cannot duplicate complaint; Trigger assembly and safety operate properly. However, assembly contains an excessive amount of lubrication (oil) - at cold temperatures, this accumulation could cause trigger parts to hang up and cause problems. Trigger pull 4 pounds, near left .005"

PARTS

Offer to clean present trigger assembly, or, if it will better restore confidence in the rifle, offer to replace trigger assembly at 500000 price as gesture of good-will.

10/15/90
JH.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE