

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 10/01/93
ENTER REPAIR NUMBER -----> 9121198 08 27 27

SERIAL NO: 7667686 NEW SERIAL NO: MODEL: 7
FROM: (CUST NUM: 051410) MOUNTAINST GA/CAL: 243
MOUNTAIN & STREAM SPORTS SHOP TYPE:
P O BOX 285 ACCESSORIES:

W/STUDS

NETTIE WV 26681
SHIPPED TO:

DATE CODES: KK 5-90
OTHER ACCESSORIES:

COMMENTS: W/OWNERS MANUAL

DATES:		TO	FROM	
RECEIVED	10 18 91	GALLERY	10 25 91	10 29 91 ENTERED BY: JJM
OPENED	10 21 91	PROD SERV	10 21 91	10 23 91 REPAIRMAN: DE
ESTIMATED	10 28 91	TAG GUNS	00 00	TYPIST:
PROMISED	00 00 00	REJECTED	00 00	CORRESPONDENT:
GO AHEAD	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: N
SHIPPED	10 31 91			

BILL TYPE N/C PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9121198 NO CHARGE EST/LETTER LSTD 10/01/93
CUSTOMER NAME: MOUNTAIN & STREAM SPORTS SHOP 08 27 32

REQUEST: WHEN COCKING BOLT TO INJECT ANOTHER SHELL WENT OFF W/O
TOUCHING THE TRIGGER

MAIN FAULT: TRIGGER PULL 4 1/4 LBS SEAR LIFT .0095

PARTS: \$ 0.00 1 92458 TRIGGER ASSEMBLY

LABOR: \$ 0.00 INSTALL NEW TRIGGER ASSEM AS GOOD WILL GESTURE IF IT WI
\$ 0.00 BETTER RESTORE CONFIDENCE IN THE RIFLE
\$ 0.00 TEST

REPAIRMAN'S INITS: DE NUM OF WKS: 02 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR