

# RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
08/22/90	08/31/90	CR 4-48	061591	788 243	R 90-22934

ACCESSORIES		L/SIGHTS	
L/WOOD			
FROM:		SHIP TO:	
RUSH CREEK GUN SHOP 7843 U S 20 WEST STOCKTON IL 61085		RUSH CREEK GUN SHOP 7843 U S 20 WEST STOCKTON IL 61085	

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:	<input type="checkbox"/> NEW	<input type="checkbox"/> SLIGHTLY WORN	<input type="checkbox"/> VERY WORN	<input type="checkbox"/> MISUSED	<input type="checkbox"/> MARRED
CUSTOMER'S REQUEST					

"Gun fires upon closing"

MAIN FAULT: cannot duplicate complaint - however, examination of trigger assembly revealed that it contains a sticky lubrication residue & maybe rusty inside also - bottom of receiver rusty.

PARTS	Send gentation to clean trigger assembly if it is possible; if not, send gentation for new trigger assembly.				
	9/14/90 JRS.				

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE