

To Remington Arms and their skilled craftsman.

Enclosed is my always trustful and faithful 700 classic 7mm. It has always performed well for me in the 24 years I've owned it. I have killed many deer and elk with this weapon. I have faithfully taken care of this rifle as much as it has done me. In the last 2 years, however, the safety mechanism has been acting strangely. When I first noticed the problem, I took it to the local gunsmith. He said it needed cleaning which he did. The following season I took it out and shot at a 4-point whitetail and it wouldn't fire. I released the bolt, tried again, and still no shot. I gave up, turned the gun away and hit the safety and the gun fired without pulling the trigger. That scared me; I can no longer trust this weapon in its present condition. Please go over this rifle to find out the problem. I want this rifle to perform the way it used to. I'm afraid to carry it with confidence, the way I used to.

Serial
Number:

A6765132

Model: **700**



RE00075741

IS: 208 347-3006

Walt Cook
KV 5/79

1/16/04 Could not duplicate the reported concern, but did find some wear on the trigger assembly. Repair trigger assembly \$20.00