

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 323520	
Name: James E Rickards Jr	Date of Purchase: 1970's	
Address (no PO Boxes): 9211 Glenloch St		
City: Philadelphia	State: Penna.	Zip: 19114
Phone (Daytime): 215-331-7554	Fax: Leave message	
E-mail Address: Bb288 @ AOL.com		
Please describe your problem: Rifle needs Safety Modification's The only way to load/unload the Rifle is w/ the Safety off. About 2 year's ago while zeroing the rifle as I was loading the rifle + closed the bolt when it discharged. Luckily it was pointed down range. I then took the rifle		
Additional Information: (Ammo type, brand, handload specifications, etc.) Remington 243 Win 100 gr. Core lock - PTD - Soft Point.		

→ See
next
Page

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

323520

Model: 700



RE00086686

could not duplicate. Trig. cam
is contaminated w/ a partially dried
and sticky lubrication residue. Replac:
TPA + clean action under bolt lock
Safety Program for \$20.00 Quote

irform.htm

1008
4015

10/3/2004