MODEL 600 SERIAL # 75538 CALIBER ,308 WIN



TO WHOM IT MAY CONCERN,

UPDATE PER CURRENT Procedures FLS 9/17/01

THIS RIFLE HAS STARTED TO RELEASE THE RIRING PIN WHEN THE SAFETY IS PUSHED FROM THE SAFE TO THE FIRE POSITION. IT DOES NOT HAPPEN EVERY TIME, BUT IT DID HAPPEN TO ME ON THE RANGE, (WITH A LIVE ROUND), AND SEVERAL TIMES AFTER, WITH AN EMPTY CHAMBER).

I BOUGHT THIS RIFLE AT A GUN SHOW AND DO NOT KNOW IF IT HAS HAD THE RECALL REWORK FOR THIS MODEL.

I HAVE OWNED THIS RIFLE FOR 11 YEARS AND THIS PROBLEM

ONLY STARTED LAST YEAR. THERE HAS BEEN NO MODIFICATION

THAT I KNOW OF BEFORE I OWNED IT, AND NONE AT ALL

SINCE I HAVE OWNED IT. IT ALSO HAS BEEN IN MY TOTAL

POSSESION SINCE I BOUGHT IT.

RETURN ADDRESS

NICHOLAS A. ROEDER

2102 OAKWOOD DR.

RICHWOOD TX. 77531

PHONE 979-265-9360 HOME 979-238-1238 WORK