

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-06704

SAFTEY LEVER BROKEN

INITIAL
JJM

CUSTOMER ORDER NO

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/17/94

02/24/94

PX 6-73

6649099

700 243

ADL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

SMITH, WALTER
3209 LUANN DR
ANTIOCH

TN 37013

SMITH, WALTER
3209 LUANN DR
ANTIOCHTN
37013

CUST NO: 092922 C-D.D-

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

85.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B5

E3

F3

REC. ASSY.

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt, safety assembly was not more than the pin to on right
operation. Examination reveals that the engagement pins have been bent
and the bottom edges of the rear safety lever have been ground. Action
and trigger assembly have been with some damage sustained.

PARTS

COMMENTS

Replaced trigger assembly &
When action at the normal
engagement test

Go ahead with action - the problem
was from a damaged

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JJM					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/94