

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047516	Description/Serial Number 6755669	Date Received - 6/11/2002
Account # - R-	Model 700 Center Fire Caliber: 30 06 BDL	Estimate Date - 6/10/2002
		Current Date - 6/17/2002
Customer JOHN SAUGRICH 115 CRESTWOOD DRIVE SARVER, PA 16055 US		Return To JOHN SAUGRICH 115 CRESTWOOD DRIVE SARVER, PA 16055 US
Phone (H) (724)-295-2571	Fax	
Phone (W)	Email crestwd@sal&giver.com	

Reported		Problems		Found	
M238	CLEAN & INSPECT	M238	CLEAN & INSPECT	M238	CLEAN & INSPECT
M992	UNINTENTIONAL FIRING	M239	REPLACE TRIGGER ASSEMBLY		

Technician's Comments	
ProblemNotes	mfg 6/74..could not duplicate concern.rust on underside of bbl.sticky residue,install new ta clean action for \$20 under bolt lock modification program per prod service

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		22	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

JOHN SAUGRICH
115 CRESTWOOD DRIVE
SARVER PA 16055



PA 160 0-10



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 7599



BILLING: PREPAID

INV#: RE00047516

ASC 3.70 J69X/J64X 14.0 01/2002