

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 Serial Number: 6755669

Name: JOHN SAUGRICH Date of Purchase: ?

Address (no PO Boxes):: 115 CRESTWOOD DRIVE

SARVER

City: State: PA Zip: 16055

Phone (Daytime): 724-295-2511 Fax:

E-mail Address: CRESTWD@SALSGIVER.COM

Please describe your problem: ACCIDENTAL DISCHARGE

WHILE UNLOADING ON A VERY COLD DAY.

ATTEN: T.D PEARSON Modify to eliminate the Bolt Lock feature

For additional safety.

Additional Information: (Ammo type, brand, handload specifications, etc.)

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm
- :: Pack your firearm for safety and to prevent handling. Preferably, ship in a firearm box. (Note: Original box)
- :: Remove all accessories from your firearm
- :: Ship your INSURED firearm by either UPS responsible for damage or loss during shipment, so you

Serial Number:

6755669

Model: 700



RE00047516

<http://www.remington.com/support/repairsvc/repairfr>

Y=6/74
Could not duplicate concern.

Post on
underside of
BBL, sticky
card.
Install new
TA, Clean
Action out
\$20.00
under
Bolt Lock
modification
program.
Quote customer
\$20.00.

FCS
6/6/02