

This Rifle fired at the time the bolt
was being shut. If you have any questions
call me at 478-552-8098.

Steven N. Lord
88 West Indian Hill Rd.
Tennille Ga. 31029

Number: 6455551

Model: 700



RE00043597

Could not duplicate
TA altered adjustments - sticky
residue - been printed

Quote new TA at \$20.00
per Bolt Lock Modification program
FCS 3/20/02