


Number: 7747859

Model: 7



RE00018812

12/14/00

Date Code ^{R5} 11/98

Recharged twice when charging belt
Upon receipt we could not duplicate
the FOB. Gun remained action & trigger
housing was dirty & small metal nyl chip
fell out of the housing during disassembly.

Replaced trigger assembly at no charge. High 23005