

12-1-94

SP-10

10/30

LE894159

Placed shotgun muzzle down with barrel perpendicular to floor - Allowed action to slam shut on a copper crusher to test for excess indent. The crusher was barely "ticked" by the inertia firing pin. I could not duplicate anything that would cause the gun to fire without the safety in the ready to fire position and pulling the trigger.

I turned the gun over to Ken Rowlands (designer that worked on SP-10) for his review.

John Supry