

BILL
SMALLEY

Attn: Service Dept.

Sir;
Enclosed is the Model 7 which I was
return to you per last week's conversation.
Again, the problem is that the rifle has two
the past fired upon pushing the safety
from the safe to the non-safe / fire position.
I would appreciate your expeditious
return to this situation, and a prompt return
piece.

Thank you very much.

Sincerely,

Bill Smalley
TAE INDUSTRIES
215 WATCHUNG AVE
ORANGE, NJ 07050

201-672-5454

