

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL LCS	CUSTOMER ORDER NO.					
DATE RECEIVED 08/22/90	DATE OPENED 08/29/90	DATE CODE DD 9-83	SERIAL NUMBER 7624325	MODEL AND GRADE 7 243		ORDER R 90-22857
ACCESSORIES W/STUDS						

FROM:	SHIP TO:
SITTON, TOMMY C RT 2 BOX 325-B HORSE SHOE NC 28742	SITTON, TOMMY C RT 2 BOX 325-B HORSE SHOE NC 28742

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW
 ☐ SLIGHTLY WORN
 ☐ VERY WORN
 ☐ MISUSED
 ☐ MARRED

CUSTOMER'S REQUEST

Left fired upon closing bolt with "safety on"

MAIN FAULT

Cannot duplicate complaint - Trigger and safety assembly operate properly - Trigger pull 4 1/2, sear lift .014"
This rifle cannot fire with safety on, because firing pin is blocked

RTS

We are prepared to return gun as received or, if it will hold victory confidence in us, you to install new trigger assembly at 1/2 normal charge. Rifle is 7 years old

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS05417