

**EMINGTON ARMS REPAIR** 

M SENDING MY DAUGHTERS REMINGTON MODLE 788 , 223 CALIBER SERIAL NO. A6145826 FOR REPAIR. ON TWO SEPERATE HUNTING HE FOLLOWING HAPPENED: A ROUND WAS CHAMBERED BUT THE WOULD NOT GO ON. THE BOLT WAS THEN LIFTED UP BUT WAS NOT BACK THEN THE BOLT WAS PUSHED BACK DOWN AND THEN THE WOULD GO ON, WITH RIFLE UNLOADED I TESTED IT AGIN AND IT SAME THING, AFTER GETTING IT TO GO ON SAFETY I PUSHED THE BACK AND FOURTH A FEW TIMES AND WHEN PUSHING IT OFF SAFETY NG PIN FIRED, I HOPE THE PROBLEM CAN BE FOUND AS THE RIFLE IS CURATE, BUT I WOULD NOT LET ANYONE USE IT NOR WOULD I SELL IT S PROBLEM.

## THANKS

**BILLY SCHULTE** RT. 5 BOX 330A VICTORIA TEXAS, 77901

Hpm 512-578-6124 Wal 512-788-3255

93 per plane with the Schult - ufits dans wel, had ufter stripped for refinishing