

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R93-14408

INITIAL CUSTOMER ORDER NO

ATTN: DENNIS SANITA

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
06/25/93	06/29/93	AR 3-68	328013		700 308 WIN
ACCESSORIES	L/SIGHTS	SCOPE BASE	L/WOOD	L/FOLLOWER	L/MAG SPRING

FROM: *Set-up file*
 SCHARNITZ, SCOTT M.
 605 BUCKINGHAM DR.
 NORTHAMPTON PA 18067

SHIP TO:
 SCHARNITZ, SCOTT M.
 605 BUCKINGHAM DR.
 NORTHAMPTON PA 18067

CUST NO: 080530 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM DATE	ESTIMATED	VIA
					V44708F

- GUN CONDITION
- NEW
 - LIGHTLY WORN
 - WORN
 - VERY WORN
 - UNREPAIRABLE
 - MARRED

REPAIR CHARGE	<i>2</i>
EXCISE	
TAX	
INSURANCE	
UPS	<i>5</i>
PARCEL POST	
TOTAL	<i>2</i>

Credit Card

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
<u>TRIGGER GROUP</u>		<i>" Rifle damaged when safety was removed "</i>				
BOLT ASSY						
BARREL ASSY.						
REC ASSY						
WOOD						
METAL						

MAIN FAULT *Upon receipt rifle in operation. Trigger would not reset. Gunner revealed that the solvent had been removed from the trigger adjustment & stop screws. Both screws had to be replaced. Trigger part tested & found to be good. Rifle adjusted & returned to gunner.*

PARTS *Mag 1968*
Trigger part 266
Gun part 007

COMMENTS *Replace trigger assembly complete at 1/2 normal replacement cost, Clean action*

Go ahead per phone 6/30/93 with customer

VISA 4128 0031 3715 3262	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PA
<i>Change</i>			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
	GALLERY TESTER	DATE	DATE	DATE	DATE	DA

OFFICE COPY

RD6925 R1