

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R93-24839

INITIAL CUSTOMER ORDER NO

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

1/11/93

11/16/93

H6639409

700 30-06

BDL

ACCESSORIES

W/STUDS

EE 10-84 2ND TIME IN

FROM:

SHIP TO:

Setup bill
SUPERIOR SHOOTERS SUPPLY
1705 WINTER
SUPERIOR

WI 54880

SUPERIOR SHOOTERS SUPPLY
1705 WINTER
SUPERIOR

WI
54880

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 008237 WILM

PROM. DATE

ESTIMATED

VIA

063103

059015

WRITE ☐

12-4-93

UPS

IN CONDITION

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

SLT ASSY.

B3

BARREL ASSY.

B4

E.C. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

IN FAULT

Sent to product service for evaluation
Unable to duplicate concern. However, examination would that
was then normal for required to more safety assembly.

RTS

COMMENTS

see 9/03643 previous
return - repair not
authorized - code 4 on bb

*Repaired trigger assembly
at N/A*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS05485