

| | | | | | |
|-----------------------|-------------------------------|---------------------|-----------------------------------------------------------------------------------------------------------|--------------------|--------------------------|
| File Number: | 20942 | | Arms Service number: | 91407 | |
| Last Name: | STATE OF COLORADO DEPT OF CO | | First Name: | | |
| Street: | 2945 US HWY 50 EAST | | City: | CANON CITY | |
| State: | CO | Zip: | 81212 | Home Ph: | |
| Work Ph: | 719-269-4415 | Product Type: | F | F A T O | |
| Type Concern: | S | PI PD P S | Concern Code: | 1007 | |
| Concern: | FIRED ON SAFE RELEASE | | | | |
| Cause Code: | 4040 | Cause: | OTHER - UNSPECIFIED OR UNDETERMINED | | |
| Assigned To: | SUPRY | Classification: | UNC | UNJ UNC UND J | |
| Settlement Detail: | REPLACED TRIGGER ASSEM AT N/C | | | Settlement Amount: | \$65.00 |
| Date Opened Rem: | 1/19/2005 | Date Opened by P/S: | 1/19/2005 | Caliber: | 308 |
| Date of Incident: | 1/11/2005 | Date Closed: | 1/27/2005 | Bullet Weight: | |
| Date to Analysis: | | Date from Analysis: | | Manufacturer: | REM |
| Model: | 700 | Serial: | F6223915 | Date Code: | |
| RAMAC: | 700 | Litigation: | <input type="checkbox"/> | PreLitigation: | <input type="checkbox"/> |
| Custody: | | Obsolete: | <input type="checkbox"/> | | |
| Time of Modification: | 10:53:17 AM | Comments: | Could not duplicated the reported concern. We did note that the trigger weight of pull screw was altered. | | |
| Date of Modification: | 1/27/2005 | | | | |