

4/16/90

TO: J.A. STEKL, Specialist

Ref my model 700 ADL 270 WIN.
serial # B6583470.

I'm SORRY THAT YOU COULD NOT
Dup. the problem. Since it occurred
twice, I FEEL that there is something
about the SAFETY switch that is NOT
WORKING properly. I will FEEL much
SAFER (my hunting buddies too!) IF the
ASSEMBLY is REPLACED with A NEW
part. Thank you for your time.

APR 20 1990

Charles R. Singleton

J.A. STEKL

Returns Address:

Charles R. Singleton
408 DAMASCUS Rd
ENTERPRISE, AL. 36330

P.S. Send me A BILL THROUGH THE US MAIL
NOT COD UPS. (cheaper + NO COD charges)

Charles R Singleton
408 Damocles Rd
Enterprise, AL 36330



Remington Arms Co, Inc
ATTN: J.A. STEKL
ILION, New York 13357