

RECEIVING AND ESTIMATING REPORT

COMMENTS

W/MAG BOX

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED 06/06/90	DATE OPENED 06/15/90	DATE CODE WI 8-76	SERIAL NUMBER A6346379	MODEL AND GRADE 700 30-06	ORDER R 90-17568
ACCESSORIES L/WOOD L/FOLLOWER L/MAG SPRING SCOPE BASE					

FROM:

THE SPORTSMAN'S CTR.
28 WAUGH DR.
HOUSTON TX 77007

SHIP TO:

THE SPORTSMAN'S CTR.
28 WAUGH DR.
HOUSTON TX 77007

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☒ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"One out of three cycles, the gun discharges (fires) when the safety is pushed off safety. Trigger pull is erratic with a 3 to 3 1/2 lb. pull difference at any set position. At times pull is down as little as 1 1/2 lb. which is unsafe".

MAIN FAULT
As received, the rifle would sometimes fire upon release of safety. Further examination revealed that trigger was improperly adjusted out of factory — trigger adjustment spring was insufficient to properly return trigger and hammer consistently. In rear — safety came on spring type glue was present on adjusting screw which inhibited proper re-adjustment of assembly.

Per phone call to Jeannie at "The Sportsman's Center" on 10/11/90 — we agreed to replace the trigger assembly at 1/2 normal price as gesture of good-will (based on age of rifle).

Replace trigger assembly at 1/2 normal price & return C.O.D. — do not charge handling charge.

REPAIRMAN GIL	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS05574