



TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00089522

Description/Serial Number

ML037700

Repairman - Robert Frink

Date Received - 12/14/2004

Account # - R-

Model 700ML Center Fire Caliber: 50

Estimate Date -

Current Date - 12/15/2004

Customer

RONALD SACCARO
12259 ARROWOOD AVE

Return To

RONALD SACCARO
12259 ARROWOOD AVE

ATON ROUGE, LA 70818 US

ATON ROUGE, LA 70818 US

Phone (H) (225)-261-6097

Fax

Phone (W)

Email

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M992 FIRED WITHOUT TOUCHING
TRIGGER

Found

M123 FORWARD TO PRODUCT SERVICE F

Repair

<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F99294	700 ML SS TRIG ASSB	1	1	0	N
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000118	GR-CLEAN	1	1	0	N
Service Total:		1	1	0	

Condition

Firing pin assembly and nipple not of our manufacture.

ProblemNotes

Action and trigger assembly very rusty / dirty, poor maintenance. Replace trigger assembly at 1/2 MSP to restore confidence. Clean action best possible.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date