

Date: 7/12/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Charles Swanson

R.E. Number: 98626

Reason for inspection: Follows Down

FIREARM

Manufacturer: Rum

Model: 700

Serial Number: ML052025

Date of Manufacture: 2/97

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: ALTERED

Other: Trg. sluggish will not return properly

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 5.5#

Manual safety: 01424

Test firing results (if applicable): —

DISPOSITION

Set screws altered. Trig. not returning properly.
Replace TPA & check over completely at 1/2 msp.

ADDITIONAL COMMENTS