

Number: 6299475

Model: 700



RE00029681

7/25/01

Date Recd ^{X5} 12/98

Rifle safety does not always engage properly
Delay fire — fired on bolt closing one time

Action & trigger assembly covered with a heavy sticky
substance. Component parts working sluggish.
Rifle poorly maintained.

Replace trigger assembly at 1/2 M5P JG Ward

1023/1008
4015