

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 98-13654

INITIAL CUSTOMER ORDER NO

PS Y30017

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

07/01/98

07/06/98

PZ 6-75

6887332

700

30-06

ADL

ACCESSORIES

FROM

SHIP TO

SPORTS WORLD
5800 S LEWIS SUITE 154
TULSA

OK 74105

SPORTS WORLD
5800 S LEWIS SUITE 154
TULSA

OK
74105

CUST NO:005259 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☒ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Function ref. is taken off

Ref 1975

Upon receipt we could not duplicate the reported concern, however, the customer advised that the trigger assembly was seized up from being exposed to water & dirt. Subsequent to some work found on trigger pin hole of the housing.

#26345

Replace the complete trigger assembly at 1/2 repair charge & clean action

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7/97

PS05614