

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 03/24/94
ENTER REPAIR NUMBER ----- 9319414 09 07 32
SERIAL NO: 6495836 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 005292) ALLISONCAR GA/CAL: 25-06
ALLISON & CAREY GUN WORKS TYPE: ADL
17311 SE STARK ACCESSORIES: W/STUDS
SCOPE BASE
L/SIGHTS

PORTLAND OR 97233
SHIPPED TO:

DATE CODES: BW 1-72
OTHER ACCESSORIES:

COMMENTS:

DATES:			TO	FROM	
RECEIVED	09 14 93	GALLERY	10 01 93	10 06 93	ENTERED BY: JJM
OPENED	09 17 93	PROD SERV	09 29 30	09 30 93	REPAIRMAN: CC
ESTIMATED	10 01 93	TAG GUNS	00 00		TYPIST:
PROMISED	00 00 00	REJECTED	00 00		CORRESPONDENT:
GO AHEAD	10 01 93	CASH RECEIVED:	\$ 0.00	BILL TYPE: I	
SHIPPED	10 14 93				
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT					

REPAIR NUMBER: 9319414 CHARGE (WORK DONE) INVOICE PRINTED 03/24/94
CUSTOMER NAME: ALLISON & CAREY GUN WORKS 09 07 38

REQUEST: GUN FIRES WHEN TAKING OFF SAFETY.
MAIN FAULT: TRIGGER ASSY. AND BOLT STOP RELEASE COVERED WITH STICKY
SUBSTANCE.

DATE OF MFG: 01-72

PARTS:	\$ 28.50	1 26345 TRIGGER ASSEM RH
	\$ 25.00	19900001 SERVICE CHARGE
	\$ 3.50	19900004 CLEAN
	\$ 3.50	19900005 TEST
LABOR:	\$ 0.00	REPLACE COMPLETE TRIGGER ASSEMBLY,
	\$ 0.00	CLEAN ACTION AT 1/2 NORMAL REPLACEMENT COST,
	\$ 0.00	AS GESTURE OF GOODWILL -
	\$ 0.00	CC/HAR

REPAIRMAN'S INITS: CC NUM OF WKS: 04 CORRESPONDENT'S INITS:
TOTAL VALUE: \$ ~~60.50~~ PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR