

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-17197

INITIAL
FPS

CUSTOMER ORDER NO

W/BTM. HALF OF SCOPE MNTS.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/31/94

06/01/94

PZ 6-75

6860308

700

7MM MAG

BDL/LH

ACCESSORIES

SCOPE BASE

W/STUDS

PRODUCT SERVICE

FROM

SHIP TO:

SCHUDER, MICHAEL
933 HANNASTOWN DR.
GREENSBURG

PA 15601

SCHUDER, MICHAEL
933 HANNASTOWN DR.
GREENSBURG

PA
15601

CUST NO: 098012 C.O.D.L

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE

PROM DATE

ESTIMATED

VIA

V5618299

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☒ MARRED

REPAIR CHARGE

20

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

\$28.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B4

BARREL ASSY.

B5

REC. ASSY.

WOOD

METAL

When bolt is closed to cock gun the firing pin is released. Two different gunsmiths have worked on it and it worked for a day or two.

MAIN FAULT

Mfg. 6-75 Unable to duplicate customer concern as rec'd. Reman active from stock found that both powder puff and trigger overtravel screws have been adjusted outside of factory. Some had gummy substance on both sides at rear causing it to stick in housing, trigger was also gummed up. We do not recommend that the trigger be adjusted outside of the factory. Metal component only require a light film of light oil to prevent sticking.

PARTS

Exchange trigger Assy at special price as gun of good will and to restore customer confidence in rifle.

COMMENTS

trigger pull minimum 3 to 5 LBS as rec'd see lift arm .006

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/94

PS05751