

To Whom it May Concern,

May 27, 19

This rifle #6860308

belongs to Michael Schuder
933 Hannastown Dr
Greensburg, PA 15601
(412) 832-3438

The problem is that when the bolt is lowered to cock the gun, the firing pin is released forward instead. I have had 2 different gun smiths look at it and both were able to get it working for a day or two.

We are moving out of State on July 3
If the gun will not be ready until after that date I will give you a

new address but if you do not have
an address mail to:

Michael Schuder
Carroll College
Department of Chemistry
Waukesha, WI 53186

after July 31 or the address on
the front before July 31. Please send
it back such that it must be signed for
and is insured.

Thank You

Michael Schuder